Technical installation, stepwise approach



Plant new to OEE measurements

Plant understands OEE, machines without networked-PLC

Measurements using


hardware IOT device

Limited amount of signals

New machines and for more complex measurements







What

Manual measurement (either on paper or digital)

Complex measuremenst using Software OPC

Advantage

Easy start without complex setup. You really get a feel for OEE

Easier setup than OPC

More complex measurements possible.
Final solution in most cases.

Disadvantage

More work for the operators Less detailed measurements

Installation is more complex than IOT

Additional information

Continu for 8-12 weeks until the whole plant understands OEE

In order to reach the final solution, a train-the-trainer program will be supported by Cierpa to ensure that the necessary knowledge is available at every plant.

Support supplied by Cierpa

We can provide train-thetrainer workshops and training materials The hardware installation of the IOT device can be performed by the technicians that are commonly utilized by the site. They only need knowledge of electrical signals and understanding of the production line layout. We provide installation manuals and signal validation tools.

For software OPC we will perform the installation remotely and we will need access to the local network and support by a system administrator.